New Wind Component Development When you think ISP, think PSI.





ISO 9001:2015 CAGE 5N884

psi-repair.com f 🏏 in You Tube


NEW WIND COMPONENT DEVELOPMENT

Blade Bearing Automatic Grease Dispenser Upgrade





PSI Xantrax Inverter



Obstruction Light



Gamesa ABB Repairs



IGBT Modules



Active Crowbars



Inverters

Eaton/Moeller EMT6 Thermistor Overload Relay



VRCC Rotor Current Controller



New Revision Snubber Board manufactured by PSI

Suzion Power Supply Model #P688W



Oil Level Sensor Rebuild




Wind Specific Equipment



Load Banks



Custom IGBT Testers








H Bridge/Hub Converter



Siemens Yaw Module



Simulations to Test Complex AEBI Functions




Label and Cobham Slip Rings



Line Reactor




GE 1.5MW IGBT



Power Factor Correction (PFC) Capacitors



For More Information Call: 800-325-4774 or Visit: psi-repair.com





psi-repair.com

 United States
 Canad

 11900 Mayfield
 PSI Re

 Livonia, Michigan
 C/O W

 48150-1710
 3950

 (800) 325-4774
 Winds

Canada—Ship to: PSI Repair Services Inc. C/0 WWD - Kuehne & Nagel 3950 Malden Road Unit #5 Windsor, Ont. CN N9C 2G4 Canada— Submit Payments to: PSI Repair Services, Inc. P.O. Box 21073 Windsor, Ontario N9B 3T4



Europe Via Paolo Emilio, 34 Roma RM 00192 Italy +39 06 454 37023