



**Repair
Renew
Remanufacture**

WIND TURBINE REPAIR CAPABILITY

UP TOWER, CABINET

- Vestas/Cotas CT modules (Top Rack)
- Gamesa ABB ACS800 Inverter
- Gamesa ABB Crowbar
- Gamesa ABB Brake Chopper
- Gamesa ABB Control Modules, RDCU, NDCU, Vibration Monitors
- GE/Eaton EMT6 Thermistor Overload Relays

UP TOWER, TOP OF NACELLE

- FAA Light
- Anemometers/Wind Vane/Wind Sensors

UP TOWER, BACK OF GENERATOR

- Vestas VRCC Power Unit
- Vestas Resistor Basket
- Vestas CT273
- Encoders

UP TOWER, ROTOR HUB


- Slip Ring
- GE Hub Converter
- Suzlon Pitch Battery Charger
- Lust/LTI/Moog Pitch Motor Drive
- GE Battery Chargers
- GE/SSB Pitch Thyristor Drive

UP TOWER, YAW DECK

- Siemens Yaw Drive

DOWN TOWER, CABINET

- Vestas/Cotas CT modules (Bottom Rack)
- Vestas CT218 Controller
- GE/Xantrex Matrix
- PSI Matrix
- Clipper/ Xantrex Matrix
- GE Line and Rotor IGBTs
- Repower Cold Climate IGBT module
- GE Control Boards, AEBI, MACC, AEPS, AEAA
- GE/Hitran Line Reactor



PSI REPAIR SERVICES, INC.

© 2022 PSI Repair Services, Inc., is a subsidiary of Phillips Service Industries,

RSI-16-116 8/16/22

psi-repair.com



ISO 9001:2008
CAGE CODE 5N884